




1/12

FIG.1



2003260-45565001

2/12

FIG.2





FIG.3



3/12

FIG.4A




FIG.4B





FIG.4C



4/12

FIG.5A




FIG.5B





FIG.5C



2002011555001

5/12

FIG.6A




FIG.6B





FIG.6C



2002011555001

6/12

FIG.7






FIG.8





8/12

FIG.10





FIG.11



9/12

FIG.12





FIG.13



10/12

FIG.14




FIG.15





FIG.16



20020124:456500F

11/12

FIG.17






FIG.18



12/12

FIG.19



10053554-03319